

## Department of Toxic Substances Control

Miriam Barcellona Ingenito, Acting Director 9211 Oakdale Avenue Chatsworth, California 91311

# SUMMARY OF VIOLATIONS

On August 5, >014, the Department of Toxic Substances Control (DTSC), California Environmental Protection Agency, conducted an inspection at:

Facility Name:	Exide Technologies Inc.				
Facility Address:	2700 Indiana Street				
	Vernon, California 90023				
EPA ID Number:	CAD 097 854 541	County:	Los Angeles		
ASSESSED AS NO. OF THE PARTY OF					

As a result of this inspection, violations of hazardous waste laws, regulations, and requirements listed on the attached pages were discovered. All violations must be corrected; the actions you must take to correct the violations are listed with each violation. If you disagree with any of the violations or proposed corrective actions listed in this Summary of Violations, you should inform DTSC. Additional violations may be found after the site visit, and these will be identified in the Violation section of the inspection report.

DTSC will provide you a complete inspection report within 65 days of the date of this inspection. You may request a meeting with DTSC to discuss the inspection, inspection report, or the Summary of Violations. The issuance of this Summary of Violations does not preclude DTSC from taking administrative, civil, or criminal action as a result of the violations noted in the Summary of Violations or violations that have not been corrected within the time provided. A false statement that compliance has been achieved is a violation of the law and punishable by a fine of not less than \$2,000 or more than \$25,000 for each occurrence. DTSC may re-inspect this facility at any time.

Company Re	epresentative Accepting Summary		DTSC Representative
Name:	JOHN S. HOGARTH	Name:	Brian Wu
Signature:	I squith \	Signature:	788Cihu
Title:	PLANT MANAGER	Title:	Environmental Scientist
Date:	8-12-14.	Date:	8-12-14'



## Department of Toxic Substances Control

Miriam Barcellona Ingenito, Acting Director 9211 Oakdale Avenue Chatsworth, California 91311

# **SUMMARY OF VIOLATIONS**

Facility Name: Exide Technologies Inc. Date: 08/12/14

SECTION I: NON - MINOR VIOLATIONS AND REQUIRED CORRECTIVE ACTION (Violations not considered Minor Violations)

You must correct the following violation(s) within the specified time frame for each violation.

1. Failure to maintain the primary barrier of the containment building to be free of significant cracks, gaps, corrosion, or other deterioration

Exide Technologies Inc. (Exide) violated California Code of Regulations, title 22, section 66265.1101(c)(1), in that on or about August 5, 2014, Exide failed to maintain the primary barrier of the containment building free of significant cracks, gaps, corrosion, or deterioration that could cause hazardous waste to be released from the primary barrier. Two areas approximately two to five feet in diameter in the concrete floor was eroded from an inch to an inch and half deep. The areas where the erosion occurred in the concrete are located at the east end of the Corridor in the Containment Building.

#### **Corrective Action:**

Effective immediately, Exide shall follow the procedures described in section 66265.1101(c) (3) to repair the erosion of the concrete that occurred in the east end of the Corridor in the Containment Building.

Page 2 of 3



### Department of Toxic Substances Control

Miriam Barcellona Ingenito, Acting Director 9211 Oakdale Avenue Chatsworth, California 91311

# **SUMMARY OF VIOLATIONS**

Facility Name: Exide Technolog	jies Inc.	Date: 08/12/2014
<del>-</del>		
<b>Continuation Sheet for SI</b>	ECTION I	海 截
NON-MINOR VIOLATIONS AN	ND REQUIRED CORREC	CTIVE ACTION
	(add title of section)	

2. Failure to Inspect and record the monitoring data, containment building, and surrounding areas

Exide Technologies Inc. (Exide) violated California Code of Regulations, title 22, section 66265.1101(c)(4), in that on or about August 11, 2014, Exide failed to inspect and record data gathered from the monitoring equipment, leak detection equipment, and the Containment Building and the area immediately surrounding the Building to detect signs of releases of hazardous waste, to wit: Exide did not conduct inspection of the above mentioned equipment, the Containment Building and the area surrounding the Containment Building.

#### **Corrective Action:**

Effective immediately, Exide shall inspect and record data gathered from the monitoring equipment, leak detection equipment, the Containment Building and he area surrounding the Containment Building, in the Operating Record.

Page 3 of 3